

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4971	4/16/76	556	Rpr counter top floor tile
4940	2/20/76	—	Rpr steam coil
3431	3/31/78	2,375	Rpl air filters in AC
4621	7/2/76	2,047	Rpl air filters AC
4250	4/2/76	2,047	Rpl air filters in AC
4242	4/9/76	683	Rpl air filters in AC
5165	9/30/76	2,047	Rpl air filters in AC
4690	12/30/77	2,263	Rpl air filters in AC
4046	2/30/77	2,047	Rpl air filters in AC
3629	7/1/77	2,047	Rpl air filters in AC
3424	3/31/77	2,047	Rpl air filters in AC
3266	12/31/76	2,047	Rpl air filters in AC
1094	9-19-75	390	Paint number on doors
0432	11/25/75	1562	Rpl two pair of doors.
3777	5/13/77	1234	Rpr stairway + balcony handrails
3687	3-10-78	718	Replace tile in laundry room
3965	6-30-78	1181	Replace heating coil
3975	5-12-78	1178	Make repairs to all handrails
3642	4-17-78	864	Self help rpl ceiling tile
5439	10-13-78	383	Rpl 60' of 1 1/4" sump pump discharge line
3941	6-2-78	1259	Rpl 20 exit signs
4072	Comp	2452	Fab wall lockers door
3367	6-1-79	495	Repl heat exchanger
3960	4-6-79	1757	Patch plaster in bathroom ledge
4500	11-28-80	211	Rpr balcony rails
1215	Comp	270	Install sidewalk adj to bldg

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
3054	2-20-8	21079	Make up to mens and locker
1025	Comp	559	Install photo dec cell
4022	Comp	227	Repair Railings
3447	3-11-83	893	Rpl Shower pan
3858	12-3-82	659	Rpl V-Blinds
4750	2-2-83	1453	patch walkway
4149	12-17-82	1784	rpl. missing aluminum screens
3612	9-2-83	13,588	Repair interiors of individual rooms
3294	5-4-84	727	Replaced missing window
4085	8-2-84	3978	Cyclic Maint
4046	10-5-84	816	Rpl V-Blinds + Brackets
3676	9-9-85	656	Rpl V-Blinds
4069	7-9-85	914	Rpl missing + damaged metal window screens
4889	8-9-85	23	Rpl 1 pc floor tile Damage Rpt
4945	8-28-85	5168	Misc structural, elect + mech rpr
6049	8-20-85	428	Rpr Door Covering - Self help
4158	Comp	506	Rpr room V-blinds thru-out Bldg.
f 585	Comp	6163	Flouring maintenance to handrails of barracks
3121	3/14/86	2075	Rpl. CV-blinds + brackets
3494	Comp	841	Relandscape lawn area around AS 4020.
3540	Comp 22886	2059	Repair leaking water line under AS-4020.
3570	9/9/86	1574	Back-fill hole under floor placed from concrete
3650	7/11/86	4189	Rpl rpp. and missing v-blind thru-out AS-4020.
3843	11/7/86	1265	Rpl. 33 unserviceable and missing v-blinds
4111	10/17/86	2346	Rpl. missing + damaged screens thru-out
4684	11/24/86	75	Rpl 2 door hinges and rpl one window screen
\$ 3659	8-12-91	2739	Rplc Comp FOR A/C SYSTEM.
3836	8/15/91	7324	MISC STRUCTURAL RPRS